

# ERRATUM DCBT33D-2S

---

Order 10895

## Etiquette

La vitesse sur le label de sécurité sur la tige  
est de 7200min<sup>-1</sup>

La vitesse Max sur la lame est de 10000min<sup>-1</sup>  
au lieu de 7200min<sup>-1</sup>

## Etiquette sur le cache de protection et sur la tige

afin d'éviter toute confusion :  
la vitesse moteur est de 9300min<sup>-1</sup>  
la vitesse de la lame est de 7200min<sup>-1</sup>  
la vitesse de la bobine est de 6800min<sup>-1</sup>

---

## Label

De snelheid op de beveiliging label  
op de stang is 7200min<sup>-1</sup>

Max snelheid op het blad is 10000min<sup>-1</sup>  
in plaats van 7200min<sup>-1</sup>

## Etiket op de beschermkap en de stang

om verwarring te voorkomen:  
het toerental van 9300min<sup>-1</sup>  
de snelheid van de blad van 7200min<sup>-1</sup>  
de snelheid van het spoel van 6800min<sup>-1</sup>

**SN : 2015.01 :001-520**

18.11.10895

Date d'arrivée – Aankomstdatum - Arrival date:

13/03/2015

Année de production - Productiejaar

Production year : 2015

---

## Label

The speed on the security label  
on the rod is 7200min<sup>-1</sup>

Max speed on the blade is 10000min<sup>-1</sup>  
instead of 7200min<sup>-1</sup>

## Label on the protective cover and the rod

to avoid confusion:  
the engine speed of 9300min<sup>-1</sup>  
the speed of the blade is 7200min<sup>-1</sup>  
the speed of the spool is 6800min<sup>-1</sup>



81, rue de Gozée  
6110 Montigny-le-Tilleul  
Belgique

Tél : 0032 71 29 70 70 Fax : 0032 71 29 70 86



**Fabriqué en Chine - Vervaardigd in China - Made  
in China - Hergesteld in China 2014**